How to calibrate an ELO USB touch panel


Applied to:

Platform	*OS version*	*XPAC utility version*
XPAC series	*All versions (WinCE6)*	*All versions*

N/A: *Not applicable to this platform and OS.*

Use a touch panel and a keyboard at the same time on XP-8x4x.

The XP-8x4x series only has two USB ports, so if you want use a touch panel and keyboard/mouse at the same time. You will need a USB hub.



LRI Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000

To calibrate an ELO USB touch panel, perform the following steps:


Step 1: Execute the calibration program.

1.1. After rebooting, click Start->Programs->USB_TOUCH->ELO-> EloVa.



Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000

1.2. Perform the calibration process.
1.2.1. Touch the “+” icons on the monitor to perform the calibration process.



LRI Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000