
How to calibrate a Penmount USB touch panel

Applies to:

Platform	*OS Version*	*PAC Utility Version*
WinPAC	*All Versions*	*All Versions*

Tips & Warnings

⚠ *To use a touch panel and a keyboard at the same time on WP-8x4x, you need a USB hub to expand the single USB port into several.*



To calibrate a Penmount USB touch panel, perform the following steps:

Step 1: Execute the calibration program.


1.1. Click My Device →System_Disk→Drivers→ USB_TOUCH → PenMount →LNK→ Calibration.




LRI Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000

1.2. Click the “**4 Points**” button.

(Pressing the “9 Points” or “16 Points” button could process a more accurate calibration)



1.3. Touch the “ ” icons on the monitor to perform the calibration process.




Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000

Step 2: Reboot your WinPAC.

2.1. Start the PAC utility and click the "**File**" → "**Reboot**" menu option.

2.2. Click the "**Yes**" button and wait for reboot.



Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000