
How to calibrate an ELO USB touch panel

Applies to:

Platform	*OS Version*	*PAC Utility Version*
WinPAC	*All Versions*	*All Versions*

Tips & Warnings


⚠ *To use a touch panel and a keyboard at the same time on WP-8x4x, you need a USB hub to expand the single USB port into several.*



To calibrate an ELO USB touch panel, perform the following steps:


Step 1: Execute the calibration program.


1.1. Click My Device →System_Disk→Drivers→ USB_TOUCH → ELO → LNK→EloVa.



LRI Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000

1.2. Touch the “**+**” icons on the monitor to perform the calibration process.






LRI Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000

Step 2: Reboot your WinPAC.

2.1. Start the Win PAC utility and click the "**File**" → "**Reboot**" menu option.

2.2. Click the "**Yes**" button and wait for reboot.



Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000