How to automatically hide the taskbar


Applies to:

Platform	*OS Version*	*PAC Utility Version*
WinPAC	*All Versions*	*All Versions*
ViewPAC	*All Versions*	*All Versions*


Depending on your preferences, you can set the taskbar to be automatically hidden when the mouse is not over. If to set the taskbar to be automatically hidden, perform the following steps:

Step 1: Set the taskbar to hidden.

1.1. click the “Properties” .




1.2. Check the “Auto Hide” option.



Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000

the taskbar will be hidden automatically**.**



LRI Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000