How to change the display type for WinPAC

Applies to:

Platform	*OS Version*	*PAC Utility Version*
WinPAC	*All Versions*	*All Versions*


The default display resolution for WP-5231/8x2x/9xxx is “800*600”. You can change the display resolution depending on your preferences by the following steps.

Tips & Warnings

If your monitor doesn’t support the display mode that you set, the monitor may not display correctly.

Step 1: Change the display resolution.

1.1. Start the PAC utility on the desktop, select the display resolution and then press “Setting” button.




LRI Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000

Step 2: Reboot your WinPAC.

2.1. Start the PAC utility on the desktop and click "**File**"→"**Reboot**".

2.2. Click the "**Yes**" button and wait for the device to reboot.



Tips & Warnings

If nothing displayed on your monitor while booting, the display settings selected on the WP-5231/8x2x/9xxx *may be not be supported by your monitor.*

Please see the document :

"w1-009-03_how_to_change_the_display_type_for_WinPAC_when_display_out_of_range_english" for more details.

Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000