How to enter characters without a keyboard


Applies to:


Platform	*OS Version*	*PAC Utility Version*
WinPAC	*All Versions*	*All Versions*
ViewPAC	*All Versions*	*All Versions*

The WinPAC/ViewPAC only has one USB port; if there is no USB hub available for a keyboard, Win CE provides an input panel to enter characters with a mouse or on touch panel.

To enter characters without a keyboard, perform the following steps:


Step 1: Click the icon circled in the picture below.






Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000

The input panel is shown as below:



Step 2: Click the key for the character you want to enter on the Input Panel.



Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000