(P)ET-2218H/S1 Quick Start

v1.0, February 2025

Packing List

In addition to this guide, the package includes the following items:

(P)ET-2218H/S1 = (P)ET-2218H + CN-1825M



(P)ET-2218H *1



CN-1825M *1



Screw Driver *1

Technical Support


service@icpdas.com

https://www.icpdas.com

Resources

How to search for drivers, manuals and spec information on ICP DAS website.

- For Mobile Web



- For Desktop Web



LRI Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000

(P)ET-2218H/S1 Assembly Chart for (P)ET-2218H and CN-1825M

1. Insert the daughter board - CN-1825M
2. Fasten the screws to secure the CN-1825M to (P)ET-2218H

1. Insert the CN-1825M



2. Fasten the screws to secure the CN-1825M

